

St. Clair Co. - S.F.

SEPA Notification of Hazardous Waste Site

United States
Environmental Protection
Agency
Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies. **210609**

IL 277

810609

ILS-000-001-170

A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name Purex Corporation
Street 5101 Clark Ave.
City Lakewood State CA Zip Code 90712

B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site Lanson Chemical Div.
Street 800 S 31st St.
City East St. Louis County _____ State IL Zip Code 62207

C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) Garfield, D.K. Corp. mgr
Safety & Envir.

Phone 213-630-7585

D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1969 To (Year) 1979

E Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item 1—Description of Site.

General Type of Waste:
Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

Source of Waste:
Place an X in the appropriate boxes.


1. ☐ Organics
2. ☐ Inorganics
3. ☒ Solvents
4. ☐ Pesticides
5. ☐ Heavy metals
6. ☒ Acids
7. ☒ Bases
8. ☐ PCBs
9. ☐ Mixed Municipal Waste
10. ☐ Unknown
11. ☐ Other (Specify)

1. ☐ Mining
2. ☐ Construction
3. ☐ Textiles
4. ☐ Fertilizer
5. ☐ Paper/Printing
6. ☐ Leather Tanning
7. ☐ Iron/Steel Foundry
8. ☐ Chemical, General
9. ☐ Plating/Polishing
10. ☐ Military/Ammunition
11. ☐ Electrical Conductors
12. ☐ Transformers
13. ☐ Utility Companies
14. ☐ Sanitary/Refuse
15. ☐ Photofinish
16. ☐ Lab/Hospital
17. ☐ Unknown
18. ☒ Other (Specify) _____

18. ☒ Other (Specify)
Paint and
cleaning compounds

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

Specific Type of Waste:
EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.



000258 JUN -9 81

JUN 12 1981

Notification of Hazardous Waste Site

Site Two

F Waste Quantity:

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☐ Landfill
4. ☒ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☒ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☐ Other (Specify) _____

Total Facility Waste Amount

cubic feet Not Available

gallons _____

Total Facility Area

square feet Not Available

acres _____

G Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☒ Suspected ☐ Likely ☐ None

Note: Items Hand I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

Possible Process and handling spills only

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees, or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name D. K. Garfield Corp mgr

Street 5101 Clark Ave

City Lakewood State CA Zip Code 90712

Signature D. K. Garfield Date 6-8-81

- ☐ Owner, Present
- ☒ Owner, Past
- ☐ Transporter
- ☐ Operator, Present
- ☐ Operator, Past
- ☐ Other

PUREX INDUSTRIES, INC.
5101 CLARK AVENUE
LAKEWOOD, CALIFORNIA 90712

June 8, 1981

US EPA Region 5
Sites Notification
Chicago, IL 60604

Gentlemen:


Enclosed are the Notification of Hazardous Waste Site forms 8900-1 for facilities which Purex Corporation or one of its divisions or subsidiaries has operated in your region some time in the past. There is a separate form for each facility in your region.

These forms are submitted as a notification of possible releases occurring during the normal process and handling of the materials checked on the form. There was, to our knowledge, no deliberate disposal of hazardous waste at any of the sites.

If you have any questions contact the undersigned at
(213) 630-7585.

Respectfully submitted,

PUREX INDUSTRIES, INC.



Douglas K. Garfield
Corporate Manager
Safety and Environment

DKG/mmj

6 Enclosure(s)

JUN 12 1981